

5,000-60,000min⁻¹

Brushless Motor EM-3060 **Motor Cord EMCD-3000-4M / 6M / 8M**

◆ Angle Type Motor Cord is available. (EMCD-3000A-4M / 6M / 8M)

→ Refer to **2-p21**

1,000-60,000min⁻¹

Brushless Motor EM-3060J **Motor Cord (Cord with Quick Disconnect) EMCD-3000J-3M / 4M / 6M / 8M**

→ Refer to **2-p22**

1,000-32,000min⁻¹

Brushless Motor EM-3030J **Motor Cord (Cord with Quick Disconnect) EMCD-3000J-3M / 4M / 6M / 8M**

→ Refer to **2-p23**

7,500min⁻¹ (*1) 30,000min⁻¹ (*2)

Speed Reducer ARG-011E (1/4 Reduction)

1,870min⁻¹ (*1) 30,000min⁻¹ (*2)

Speed Reducer ARG-021E (1/16 Reduction)

*May be connected between the motor and the spindle as required for increased torque.



Air Line Kit AL-0201
*Cooled-air is supplied.


→ Refer to **2-p32**

Compressor



Control Unit NE211 NE211-OP1

→ Refer to **2-p29**



Selector Unit NE212

*Single motor can only be operated at the same time. No simultaneous operation.

→ Refer to **2-p31**

7,500min⁻¹ (*1) 30,000min⁻¹ (*2)

Speed Reducer ARG-2504N (1/4 Reduction)

1,870min⁻¹ (*1) 30,000min⁻¹ (*2)

Speed Reducer ARG-2516N (1/16 Reduction)

*May be connected between the motor and the spindle as required for increased torque.

5,000-50,000min⁻¹

Brushless Motor (Cord with Quick Disconnect) EM25N-5000-J4

→ Refer to **2-p26**

***Do not exceed the maximum motor speed recommendation for the spindles. Excess speed will dramatically reduce bearing life.**

*1 : Maximum rotating speed at the cutting tool.
*2 : Maximum allowable motor speed for the spindle.